



Concrete grinders and scabblers, while commercially available and less expensive than replacement, are more costly than the Precision Concrete Cutting method. Grinders are also unable to reach the edges of the sidewalk or grind the sidewalk level with the next concrete panel, so the trip hazard often remains.

Not only can Precision Concrete Cutting reach the edges of every sidewalk, we can remove trip hazards from virtually any angle and at any location. Trip hazards caused by cracked concrete or located in hard-to-reach places such as in gutters or adjacent to a wall will be eliminated without any damage to nearby objects.


Our method takes very little time, with minimal disruptions to pedestrians using the sidewalk. The result is a safe, clean-cut walking path provided at a greater value than any other method.

View our animated demo, showing our clean, fast and cost effective trip hazard removal solution!




Our patented process slices the trip hazard away!

## FIND A LOCATION




SEARCH

### REPAIRED WITH GRINDERS AND SCABLERS



### REPAIRED WITH PRECISION CONCRETE CUTTING METHOD



### WHAT'S WRONG WITH SIDEWALK GRINDING